Firmware-Update for managed Switch TBEN-Lx-SE-M2

Fieldbus Integration for managed switches is integrated in firmware versions >= 2.0. Existing devices can be upgraded. As there are changes in the internal data structure of the switch, when updating from a version <2.0, an intermediate step is required:

• V1.2.10.0
The intermediate version. **Only after this firmware has been successfully installed, a version >=V2.0.0.0 can be successfully installed.** V1.2.10 does not apply any functional changes compared to its predecessor 1.2.9. Please note: Update from any version <1.2.10 to 1.2.10 is possible.

• V2.0.5.0
The latest firmware including fieldbus functions.